Infrastructure - Task #6367

Update drive firmware on P2-1 UCSB SAN Array

2014-09-08 20:19 - Nick Outin

Status:	New	**Start date:**	2014-09-08
Priority:	Normal	**Due date:**	
Assignee:	Nick Outin	**% Done:**	0%
Category:	Hardware	**Estimated time:**	2.00 hours
Target version:			
Milestone:	None	**Story Points:**	
Product Version:	*		

Description

The last array on the UCSB SAN, P2-1, needs firmware updates. This will require 2 hours of downtime for cn-ucsb-1, search, and mn-stage-ucsb-3. After inquiring about the downtime on IRC Chris Jones recommended doing it while UCSB is out of RR, during the CCI 1.4.0 release.

Related issues:

Related to Infrastructure - Story #5533: CCI 1.4.0 Release	**Closed**